

Ericsson PE Delhi NCR 23 Alarm Handling SOP for ALARM_7141

Node: Ericsson-PE-Delhi-NCR-23 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_7141

Description

This SOP outlines the procedures for handling the ALARM_7141 (Minor Severity) on the Ericsson Provider Edge Router (Node ID: Ericsson-PE-Delhi-NCR-23).

Potential Root Causes

Cause	Probability
Misconfigured BGP Peer	Medium
Interface Down/Duplicated IP	High
Route Leak or Misconfigured Route Reflectors	Low

Diagnostic Commands

```
show bgp all summary
show ip bgp neighbors
show ip interface brief
show ip route
show ip bgp community-lists
```

Resolution Steps

- Step 1: {'Step': 'Verify and Correct BGP Peer Configuration', 'CLI_Command': 'show bgp all summary | include '}
- Step 2: {'Step': 'Verify Interface Status and IP Address', 'CLI_Command': 'show ip interface brief'}
- Step 3: {'Step': 'Verify and Correct Route Reflectors and Route Leaks', 'CLI_Command': 'show ip bgp community-lists'}
- Step 4: {'Step': 'Clear BGP Sessions', 'CLI_Command': 'clear bgp *'}
- Step 5: {'Step': 'Re-Verify BGP Peer and Route Reflectors', 'CLI_Command': 'show bgp all summary | include '}

Post-Check Verification

```
show bgp all summary
show ip bgp neighbors
```

```
show ip interface brief
show ip route
```