

Ericsson PE Router - Major Alarm ALARM_8916 SOP

Node: Ericsson-PE-Delhi-NCR-23 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_8916

Description

This SOP outlines the steps to diagnose and resolve the Major Alarm ALARM_8916 on Ericsson Provider Edge Router Ericsson-PE-Delhi-NCR-23.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Misconfigured QoS Policies	Medium
Hardware Fault	Low

Diagnostic Commands

```
show cpu utilization
show qos policy
show hardware status
show alarm history
```

Resolution Steps

- Step 1: {'Step': 'Verify CPU Utilization', 'Description': 'Check CPU utilization levels and take necessary actions to reduce load.', 'CLI_Command': 'show cpu utilization'}
- Step 2: {'Step': 'Review QoS Policies', 'Description': 'Review QoS policies for misconfigurations and correct as necessary.', 'CLI_Command': 'show qos policy'}
- Step 3: {'Step': 'Hardware Inspection', 'Description': 'Perform a hardware inspection to identify any potential faults.', 'CLI_Command': 'show hardware status'}
- Step 4: {'Step': 'Alarm History Review', 'Description': 'Review alarm history to identify any recurring issues.', 'CLI_Command': 'show alarm history'}
- Step 5: {'Step': 'Hardware Replacement', 'Description': 'Replace faulty hardware as necessary.', 'CLI_Command': 'no shutdown'}

Post-Check Verification

```
show cpu utilization
show qos policy
```

```
show hardware status
```

```
show alarm history
```