

Standard Operating Procedure for Ericsson PE Router Alarm ALARM_4741

Node: Ericsson-PE-Mumbai-MH-40 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_4741

Description

Alarm ALARM_4741 is a critical alarm on the Ericsson Provider Edge Router (PE) indicating a severe issue that requires immediate attention.

Potential Root Causes

Cause	Probability
High CPU utilization due to software bugs or configuration issues	High
Memory leak due to faulty software or hardware	Medium
Interoperability issues with other network devices	Low

Diagnostic Commands

```
show cpu utilization
show memory statistics
show interface statistics
show log messages | include ALARM_4741
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU utilization', 'Action': 'Run show cpu utilization command', 'Expected_Result': 'CPU utilization should be within normal limits', 'CLI_Command': 'show cpu utilization'}
- Step 2: {'Step': '2. Check memory statistics', 'Action': 'Run show memory statistics command', 'Expected_Result': 'Memory usage should be within normal limits', 'CLI_Command': 'show memory statistics'}
- Step 3: {'Step': '3. Check interface statistics', 'Action': 'Run show interface statistics command', 'Expected_Result': 'Interface statistics should be within normal limits', 'CLI_Command': 'show interface statistics'}
- Step 4: {'Step': '4. Check log messages', 'Action': 'Run show log messages | include ALARM_4741 command', 'Expected_Result': 'Alarm messages should be cleared', 'CLI_Command': 'show log messages | include ALARM_4741'}

Step 5: {'Step': '5. Restart the router', 'Action': 'Run reboot command', 'Expected_Result': 'Alarm should be cleared', 'CLI_Command': 'reboot'}

Post-Check Verification

```
show cpu utilization
show memory statistics
show interface statistics
show log messages | include ALARM_4741
```