

Huawei Access Switch ALARM_3422 Warning Alarm SOP

Node: Huawei-Access-Bangalore-KA-62 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_3422

Description

This SOP outlines the steps to diagnose and resolve the ALARM_3422 warning alarm on Huawei Access Switch Node ID: Huawei-Access-Bangalore-KA-62.

Potential Root Causes

Cause	Probability
Incorrect configuration of the access switch	High
Hardware failure of the access switch	Medium
Software issue on the access switch	Low

Diagnostic Commands

```
display current-configuration | include interface GigabitEthernet 0/1/0
display device-managed-object | include GigabitEthernet 0/1/0
diag snmp-agent trap enable
```

Resolution Steps

- Step 1: { 'step': 'Check the interface configuration', 'action': "Run the command 'display current-configuration | include interface GigabitEthernet 0/1/0' to verify the interface configuration. If the configuration is incorrect, correct it and reload the interface." }
- Step 2: { 'step': 'Verify hardware status', 'action': "Run the command 'display device-managed-object | include GigabitEthernet 0/1/0' to check the hardware status of the interface. If the hardware is faulty, replace it with a new one." }
- Step 3: { 'step': 'Check software version', 'action': "Run the command 'display version' to check the software version of the access switch. If the software version is outdated, upgrade it to the latest version." }
- Step 4: { 'step': 'Reload the interface', 'action': "Run the command 'reload interface GigabitEthernet 0/1/0' to reload the interface." }

Post-Check Verification

```
display interface GigabitEthernet 0/1/0
```

```
display device-managed-object | include GigabitEthernet 0/1/0  
diag snmp-agent trap enable
```