

Huawei Access Switch Alarm Resolution SOP - ALARM_9251

Node: Huawei-Access-Bangalore-KA-62 | **Vendor:** Huawei | **Severity:** Critical | **Alarm Code:** ALARM_9251

Description

This Standard Operating Procedure (SOP) outlines the steps to resolve ALARM_9251 on Huawei Access Switch Node ID: Huawei-Access-Bangalore-KA-62.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Buffer Overflow Issue	Medium
Hardware Fault	Low

Diagnostic Commands

```
display cpu-profile
display buffer statistics
display hardware
display system
display diagnostic-information
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU Utilization', 'Action': 'Run display cpu-profile command to check CPU utilization levels. If CPU utilization is above 80%, proceed to Step 2.', 'CLI_Commands': 'display cpu-profile'}
- Step 2: {'Step': '2. Clear Buffer Cache', 'Action': 'Run clear buffer cache command to clear buffer cache and resolve buffer overflow issue.', 'CLI_Commands': 'clear buffer cache'}
- Step 3: {'Step': '3. Replace Faulty Hardware', 'Action': 'In case of hardware fault, replace the faulty hardware component and verify the issue is resolved.', 'CLI_Commands': 'display hardware'}

Post-Check Verification

```
display cpu-profile
display buffer statistics
```

display hardware

display system