

Huawei Access Switch Node - Bangalore KA-66

ALARM_4133 Major Alarm Resolution SOP

Node: Huawei-Access-Bangalore-KA-66 | **Vendor:** Huawei | **Severity:** Major | **Alarm Code:** ALARM_4133

Description

This SOP outlines the procedures to diagnose, resolve, and verify the fix for the Huawei Access Switch Node Bangalore KA-66 experiencing a Major ALARM_4133.

Potential Root Causes

Cause	Probability
Hardware failure in the switch's line card	High
Software bug in the switch's firmware	Medium
Incorrect configuration settings	Low

Diagnostic Commands

```
display this
diagnostic diagnose system
display faultman fault brief
```

Resolution Steps

- Step 1: {'Step': 'Power cycle the switch', 'Action': "Execute 'shutdown' command followed by 'no shutdown' to restart the switch."}
- Step 2: {'Step': 'Verify the hardware', 'Action': 'Physically inspect the switch and its components, and check for any signs of physical damage or malfunction.'}
- Step 3: {'Step': "Check the switch's configuration", 'Action': "Execute 'display current-configuration' and 'display startup-configuration' commands to check for any incorrect or mismatched configuration settings."}
- Step 4: {'Step': "Update the switch's firmware", 'Action': "Execute 'system update' command to check for and install any available firmware updates."}

Post-Check Verification

```
display faultman fault detailed
display this
diagnostic diagnose system
```