

Huawei Access Switch Alarm Resolution SOP: ALARM_8997

Node: Huawei-Access-Bangalore-KA-66 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_8997

Description

This SOP outlines the steps to diagnose and resolve the ALARM_8997 issue on the Huawei Access Switch located at Bangalore-KA-66.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Bug	Medium
Configuration Issue	Low

Diagnostic Commands

```
display current-configuration | include ALARM_8997
show system internal alarm-module info
display diagnostic-logs | include ALARM_8997
```

Resolution Steps

Step 1: {'Step': 'Power cycle the switch', 'Action': 'Power off the switch, wait for 30 seconds, and then power it on.'}

Step 2: {'Step': 'Check and clear logs', 'Action': '"Clear the system logs using the 'clear system internal alarm-module logs' command.'}

Step 3: {'Step': 'Reboot the switch in diagnostic mode', 'Action': '"Reboot the switch using the 'reload' command with the option to enter diagnostic mode.'}

Step 4: {'Step': 'Verify the issue', 'Action': 'Check the logs and verify if the alarm is still present.'}

Post-Check Verification

```
display current-configuration | include ALARM_8997
show system internal alarm-module info
display diagnostic-logs | include ALARM_8997
```