

Huawei Access Switch Alarm Resolution SOP for ALARM_4398

Node: Huawei-Access-Bangalore-KA-68 | **Vendor:** Huawei | **Severity:** Major | **Alarm Code:** ALARM_4398

Description

This SOP outlines the steps to resolve the ALARM_4398 on Huawei Access Switch Node ID: Huawei-Access-Bangalore-KA-68, which is a Major severity alarm.

Potential Root Causes

Cause	Probability
Incorrect configuration of VLANs or VLAN trunking	High
Hardware failure of the switch or one of its components	Medium
Software issues with the switch or its firmware	Low

Diagnostic Commands

```
display version | include ALARM_4398
display fault | include ALARM_4398
display interface info | include trunk|tagged
display vlan | include trunk|tagged
```

Resolution Steps

- Step 1: {'Step': '1. Check the switch configuration', 'Action': 'verify the VLAN configuration and trunking settings'}
- Step 2: {'Step': '2. Check for hardware issues', 'Action': 'run a hardware diagnostic test using the command: diagnose hwtest', 'CLI_Commands': ['diagnose hwtest']}
- Step 3: {'Step': '3. Check for software issues', 'Action': 'check for firmware updates and apply the latest version'}
- Step 4: {'Step': '4. Clear the alarm', 'Action': 'use the command: reset fault '}
- Step 5: {'Step': '5. Verify the fix', 'Action': 'use the command: display fault | include ALARM_4398'}

Post-Check Verification

```
display fault | include ALARM_4398
display interface info | include trunk|tagged
```

```
display vlan | include trunk|tagged
```