

Huawei Access Switch SOP for Alarm Code

ALARM_5855

Node: Huawei-Access-Bangalore-KA-68 | **Vendor:** Huawei | **Severity:** Major | **Alarm Code:** ALARM_5855

Description

This SOP outlines the steps to diagnose and resolve the ALARM_5855 issue on Huawei Access Switch Node ID: Huawei-Access-Bangalore-KA-68

Potential Root Causes

Cause	Probability
High CPU utilization due to software bugs or configuration issues	High
Misconfigured port settings or duplex mismatch	Medium
Hardware failure or faulty optics	Low

Diagnostic Commands

```
display version
display diagnostic result
display cpu utilization
display interface statistics
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU utilization and CPU temperature', 'Action': 'Run command: display cpu utilization and display cpu temperature'}
- Step 2: {'Step': '2. Check for software bugs or configuration issues', 'Action': 'Run command: display version and check for firmware updates'}
- Step 3: {'Step': '3. Verify port settings and duplex settings', 'Action': 'Run command: display interface statistics and verify port settings'}
- Step 4: {'Step': '4. Replace faulty optics or hardware', 'Action': 'Perform hardware replacement'}

Post-Check Verification

```
display cpu utilization
display cpu temperature
display interface statistics
```

```
display diagnostic result
```