

SOP: Troubleshooting Huawei Access Switch Node Bangalore-KA-68 (Huawei-Access-Bangalore-KA-68)

Node: Huawei-Access-Bangalore-KA-68 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_8625

Description

ALARM_8625: Minor alarm triggered on Huawei Access Switch Node Bangalore-KA-68 (Huawei-Access-Bangalore-KA-68) indicating a potential issue with the switch's functionality.

Potential Root Causes

Cause	Probability
Optical Port Issues	Medium
Optical Fiber Damage	Low
Switch Configuration Errors	High

Diagnostic Commands

```
display device
display optical-ports
display fiber-status
display switch-configuration
```

Resolution Steps

- Step 1: {'Step': '1. Verify switch configuration', 'Action': 'check if configuration is correct using display switch-configuration command.'}
- Step 2: {'Step': '2. Check optical port status', 'Action': 'use display optical-ports command to verify if optical ports are functioning correctly.'}
- Step 3: {'Step': '3. Check fiber status', 'Action': 'use display fiber-status command to verify if fibers are intact and not damaged.'}
- Step 4: {'Step': '4. Reset switch to default configuration', 'Action': 'use reset system default command to reset switch to default configuration.'}

Post-Check Verification

```
display device
display optical-ports
```

```
display fiber-status  
display switch-configuration
```