

# Huawei Access Switch Alarm Resolution - ALARM\_3568

**Node:** Huawei-Access-Bangalore-KA-74 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM\_3568

## Description

This Standard Operating Procedure (SOP) outlines the steps to diagnose and resolve the Huawei Access Switch Alarm ALARM\_3568, a warning severity alarm.

## Potential Root Causes

| Cause                                 | Probability |
|---------------------------------------|-------------|
| Optical Transceiver Issues            | High        |
| Fiber Optic Cable Damage              | Medium      |
| Huawei Access Switch Hardware Failure | Low         |

## Diagnostic Commands

```
display device internal info
display fiber optic cable info
display transceiver info
```

## Resolution Steps

- Step 1: {'Step': 'Check Optical Transceiver Connection', 'Action': 'Verify the optical transceiver is properly connected to the Huawei Access Switch and check for any signs of damage.'}
- Step 2: {'Step': 'Replace Optical Transceiver', 'Action': 'If the transceiver is damaged, replace it with a new one and verify the alarm is cleared.', 'CLI\_Commands': ['replace transceiver 1/1/1', 'verify transceiver 1/1/1']}
- Step 3: {'Step': 'Check Fiber Optic Cable', 'Action': 'Verify the fiber optic cable is securely connected to the Huawei Access Switch and check for any signs of damage.'}
- Step 4: {'Step': 'Replace Fiber Optic Cable', 'Action': 'If the cable is damaged, replace it with a new one and verify the alarm is cleared.', 'CLI\_Commands': ['replace fiber optic cable 1/1/1', 'verify fiber optic cable 1/1/1']}
- Step 5: {'Step': 'Perform Huawei Access Switch Reset', 'Action': 'If the alarm persists, reset the Huawei Access Switch and verify the alarm is cleared.', 'CLI\_Commands': ['reset system', 'verify system status']}

## Post-Check Verification

```
display alarm info  
display system status
```