

Huawei Access Switch Major Alarm Resolution SOP (ALARM_3724)

Node: Huawei-Access-Bangalore-KA-76 | **Vendor:** Huawei | **Severity:** Major | **Alarm Code:** ALARM_3724

Description

This SOP outlines the procedures to diagnose and resolve a Major Alarm (ALARM_3724) on the Huawei Access Switch (Node ID: Huawei-Access-Bangalore-KA-76).

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Misconfigured VLANs	Medium
Hardware Failure (e.g., Fan or Power Supply)	Low

Diagnostic Commands

```
display alarm-information
display cpu-usage
display vlan
display interface
```

Resolution Steps

- Step 1: {'Step': 'Check CPU Utilization', 'Action': 'Run command: display cpu-usage', 'Expected_Result': 'CPU utilization below 70%'}
- Step 2: {'Step': 'Verify VLAN Configuration', 'Action': 'Run command: display vlan', 'Expected_Result': 'VLANs are properly configured'}
- Step 3: {'Step': 'Swap Faulty Hardware (if necessary)', 'Action': 'Physically swap out faulty hardware (e.g., fan or power supply)', 'Expected_Result': 'Alarm resolves'}
- Step 4: {'Step': 'Reset Switch Configuration (if necessary)', 'Action': 'Run command: reset system', 'Expected_Result': 'Switch reboots and alarm resolves'}

Post-Check Verification

```
display alarm-information
display cpu-usage
```

```
display vlan  
display interface
```