

Huawei Access Switch Alarm Resolution SOP: ALARM_4283

Node: Huawei-Access-Bangalore-KA-76 | **Vendor:** Huawei | **Severity:** Major | **Alarm Code:** ALARM_4283

Description

This SOP outlines the steps to resolve a Major alarm on Huawei Access Switch Node ID: Huawei-Access-Bangalore-KA-76.

Potential Root Causes

Cause	Probability
Hardware failure in the switch	High
Software glitch in the switch firmware	Medium
Configuration issue in the switch	Low

Diagnostic Commands

```
display version
display tech-support
debug enable
debug bgp
```

Resolution Steps

Step 1: {'Step': '1. Check the switch logs for any error messages', 'Action': 'display log', 'Notes': 'Check the switch logs for any error messages related to the alarm.'}

Step 2: {'Step': '2. Check the switch configuration for any issues', 'Action': 'display current-configuration', 'Notes': 'Check the switch configuration for any issues that may be causing the alarm.'}

Step 3: {'Step': '3. Check the switch hardware for any issues', 'Action': 'display hardware', 'Notes': 'Check the switch hardware for any issues that may be causing the alarm.'}

Step 4: {'Step': '4. Upgrade the switch firmware if necessary', 'Action': 'upgrade firmware', 'Notes': 'Upgrade the switch firmware if necessary to resolve the issue.'}

Post-Check Verification

```
display version
display tech-support
```

```
ping 192.168.1.1
```