

Huawei Access Switch SOP - ALARM_7980: Minor Alarm on Node Huawei-Access-Bangalore-KA-76

Node: Huawei-Access-Bangalore-KA-76 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_7980

Description

This SOP outlines the steps to diagnose and resolve the ALARM_7980 (Minor Alarm) on Huawei Access Switch Node Huawei-Access-Bangalore-KA-76.

Potential Root Causes

Cause	Probability
Incorrect Configuration	Medium
Hardware Failure	Low
Software Bug	High

Diagnostic Commands

```
display current-configuration | include alarm 7980
show alarm 7980 detail
show log 7980 | last 10
ping to verify connectivity
```

Resolution Steps

- Step 1: Step 1: Verify configuration using display current-configuration | include alarm 7980 command. Check for any incorrect settings.
- Step 2: Step 2: If incorrect configuration is found, correct the settings using the appropriate CLI command.
- Step 3: Step 3: If hardware failure is suspected, replace the faulty component and verify the system.
- Step 4: Step 4: If software bug is suspected, upgrade the software to the latest version and verify the system.

Post-Check Verification

```
display current-configuration | include alarm 7980 to verify corrected configuration
show alarm 7980 detail to verify alarm status
```

```
show log 7980 | last 10 to verify log entries
```