

Huawei Access Switch Alarm SOP for ALARM_6084

Node: Huawei-Access-Chennai-TN-100 | **Vendor:** Huawei | **Severity:** Critical | **Alarm Code:** ALARM_6084

Description

This SOP describes the steps to troubleshoot and resolve the ALARM_6084 Critical alarm on the Huawei Access Switch in Chennai, TN-100.

Potential Root Causes

Cause	Probability
Hardware failure in the switch or one of its components	High
Software issue or configuration error	Medium
Environmental factors such as temperature or power issues	Low

Diagnostic Commands

```
display current-configuration
display system internal info
display device diagnose result
show tech-support
```

Resolution Steps

- Step 1: {'Step': '1. Verify the alarm log for recent events', 'Action': 'show alarm log'}
- Step 2: {'Step': '"2. Check the switch's hardware and components for any signs of damage or malfunction"', 'Action': 'system internal info'}
- Step 3: {'Step': '3. Run the diagnostic commands to identify any software issues or configuration errors', 'Action': '['display current-configuration', 'display device diagnose result']'}
- Step 4: {'Step': '4. If a software issue is identified, upgrade or downgrade the software as necessary', 'Action': 'upgrade software'}
- Step 5: {'Step': '5. If a hardware issue is identified, replace the faulty component or the entire switch as necessary', 'Action': 'replace hardware component'}
- Step 6: {'Step': '6. Verify that the alarm has cleared and the switch is functioning correctly', 'Action': 'show alarm log'}

Post-Check Verification

```
show alarm log
```

```
display system internal info  
display device diagnose result  
show tech-support
```