

Huawei Access Switch - Alarm 3064 (Critical) - Node ID: Huawei-Access-Chennai-TN-84

Node: Huawei-Access-Chennai-TN-84 | **Vendor:** Huawei | **Severity:** Critical | **Alarm Code:** ALARM_3064

Description

Alarm 3064 indicates a critical issue with the Huawei Access Switch, Node ID: Huawei-Access-Chennai-TN-84. This alarm requires immediate attention to prevent network downtime.

Potential Root Causes

Cause	Probability
Hardware failure in the switch	High
Configuration error in the switch	Medium
Software issue in the switch	Low

Diagnostic Commands

```
display version | include 'Huawei-Access-Chennai-TN-84'
display hardware | include 'Switch'
display cpu-memory | include 'Memory'
display trap | include 'Alarm 3064'
```

Resolution Steps

- Step 1: {'Step': '1. Check the switch logs for any error messages related to Alarm 3064.', 'Action': "display log | include 'Alarm 3064'"}
- Step 2: {'Step': '2. Check the switch configuration for any errors or inconsistencies.', 'Action': "display current-configuration | include 'Huawei-Access-Chennai-TN-84'"}
- Step 3: {'Step': '3. Check the switch hardware for any issues or failures.', 'Action': "display hardware | include 'Switch'"}
- Step 4: {'Step': '4. If the issue is software-related, try to upgrade the switch software to the latest version.', 'Action': 'system software package install /huawei/tn84/upgrade.swu'}
- Step 5: {'Step': '5. If the issue persists after upgrading the software, try to reset the switch to its default configuration.', 'Action': 'system reset default'}

Post-Check Verification

```
display version | include 'Huawei-Access-Chennai-TN-84'  
display trap | include 'Alarm 3064'  
display log | include 'Alarm 3064'
```