

Huawei Access Switch Alarm Handling SOP for ALARM_8212

Node: Huawei-Access-Chennai-TN-84 | **Vendor:** Huawei | **Severity:** Critical | **Alarm Code:** ALARM_8212

Description

This SOP outlines the steps to handle the Critical alarm ALARM_8212 on Huawei Access Switch Node ID: Huawei-Access-Chennai-TN-84.

Potential Root Causes

Cause	Probability
Hardware failure in the switch	High
Optical fiber cut or damage	Medium
Software issue or configuration error	Low

Diagnostic Commands

```
display version
display diagnose info
display fiber optic status
```

Resolution Steps

Step 1: {'Step': 'Power cycle the switch', 'Action': 'Execute the command: power off and then power on the switch'}

Step 2: {'Step': 'Check and replace faulty hardware', 'Action': 'Use the command: display hardware info to identify faulty components and replace them as necessary'}

Step 3: {'Step': 'Verify and correct configuration', 'Action': 'Use the command: display current-configuration to verify configuration and correct any errors'}

Step 4: {'Step': 'Check and repair optical fiber', 'Action': 'Use the command: display fiber optic status to identify damaged fibers and repair or replace them as necessary'}

Post-Check Verification

```
display version
display diagnose info
display fiber optic status
```