

Huawei Access Switch Node - Chennai-TN-84 Alarm Handling SOP

Node: Huawei-Access-Chennai-TN-84 | **Vendor:** Huawei | **Severity:** Critical | **Alarm Code:** ALARM_8475

Description

This Standard Operating Procedure (SOP) outlines the steps to handle the ALARM_8475 (Critical) on the Huawei Access Switch Node, Chennai-TN-84.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Bug	Medium
Misconfiguration	Low

Diagnostic Commands

```
display version
display diagnostic result
debug enable
debug switch port
```

Resolution Steps

- Step 1: {'Step': '1. Check the system logs for any error messages', 'Action': 'show log'}
- Step 2: {'Step': '2. Check the hardware for any signs of damage', 'Action': 'check hardware'}
- Step 3: {'Step': '3. Run the diagnostic commands to identify the root cause', 'Action': 'display diagnostic result'}
- Step 4: {'Step': '4. Reboot the switch if necessary', 'Action': 'reload'}
- Step 5: {'Step': '5. Check for any software updates', 'Action': 'check software version'}
- Step 6: {'Step': '6. Apply the necessary configuration changes', 'Action': 'configure'}

Post-Check Verification

```
verify version
verify diagnostic result
```

```
verify switch port status
```