

Huawei Access Switch Alarm Resolution SOP

(ALARM_6694)

Node: Huawei-Access-Chennai-TN-92 | **Vendor:** Huawei | **Severity:** Critical | **Alarm Code:** ALARM_6694

Description

This SOP describes the steps to identify and resolve the Huawei Access Switch alarm ALARM_6694, which is a critical alarm indicating a potential hardware failure on the Huawei-Access-Chennai-TN-92 node.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Configuration Issue	Medium
Software Bug	Low

Diagnostic Commands

```
display version
display diagnose
display fault-manage alarm info
```

Resolution Steps

- Step 1: {'Step': 'Verify the alarm log', 'Action': "Run the command 'display fault-manage alarm info' to obtain the alarm log"}
- Step 2: {'Step': 'Check the hardware', 'Action': "Run the command 'display diagnose' to check the hardware status"}
- Step 3: {'Step': 'Reboot the device', 'Action': "Run the command 'reboot system' to reboot the device"}
- Step 4: {'Step': 'Verify the alarm is cleared', 'Action': "Run the command 'display fault-manage alarm info' to verify the alarm is cleared"}

Post-Check Verification

```
display fault-manage alarm info
display diagnose
display version
```