

Huawei Access Switch - ALARM_9651 SOP

Node: Huawei-Access-Chennai-TN-92 | **Vendor:** Huawei | **Severity:** Critical | **Alarm Code:** ALARM_9651

Description

This Standard Operating Procedure (SOP) outlines the steps to diagnose and resolve the ALARM_9651 (Critical) on the Huawei Access Switch Node ID: Huawei-Access-Chennai-TN-92.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Hardware Failure	Medium
Software Issue	Low

Diagnostic Commands

```
display cpu-system
display cpu-task
display interface brief
display hardware version
```

Resolution Steps

- Step 1: {'Step': 'Reload the Switch', 'Action': 'reload', 'Description': 'Reload the switch to clear the system memory and resolve CPU utilization issues.'}
- Step 2: {'Step': 'Replace Faulty Hardware', 'Action': 'hw-module replace', 'Description': 'Replace the faulty hardware component to resolve hardware failure issues.'}
- Step 3: {'Step': 'Upgrade Software', 'Action': 'upgrade software', 'Description': 'Upgrade the software to the latest version to resolve software issues.'}

Post-Check Verification

```
display cpu-system
display interface brief
ping
```