

Huawei Access Switch Node Chennai TN-94 Critical Alarm Resolution SOP

Node: Huawei-Access-Chennai-TN-94 | **Vendor:** Huawei | **Severity:** Critical | **Alarm Code:** ALARM_1399

Description

Critical Alarm ALARM_1399 on Huawei Access Switch Node Chennai TN-94. This SOP outlines the steps to identify, diagnose, and resolve the root cause of the alarm.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Bug	Medium
Misconfiguration	Low

Diagnostic Commands

```
display fault
display alarm
display device
display interface
display system
debug switch
```

Resolution Steps

- Step 1: {'Step': 'Run diagnostic commands to identify the root cause', 'Action': 'Run the diagnostic commands listed above and analyze the output to determine the root cause'}
- Step 2: {'Step': 'Replace faulty hardware', 'Action': 'Replace the faulty hardware component identified in the diagnostic phase and verify that the alarm is cleared'}
- Step 3: {'Step': 'Apply software patch or update', 'Action': 'Apply the latest software patch or update to address the software bug identified in the diagnostic phase and verify that the alarm is cleared'}
- Step 4: {'Step': 'Reconfigure the switch', 'Action': 'Reconfigure the switch to address the misconfiguration identified in the diagnostic phase and verify that the alarm is cleared'}

Post-Check Verification

```
display fault  
display alarm  
display device  
display interface  
display system
```