

Huawei Access Switch Alarm Handling:

ALARM_1540

Node: Huawei-Access-Delhi-NCR-12 | **Vendor:** Huawei | **Severity:** Critical | **Alarm Code:** ALARM_1540

Description

This SOP outlines the procedure for handling a critical alarm (ALARM_1540) on the Huawei Access Switch (Node ID: Huawei-Access-Delhi-NCR-12) in a timely and efficient manner.

Potential Root Causes

Cause	Probability
Physical Layer Issues (Cable Damage or Loose Connections)	High
Optical Transceiver Issues (Misaligned or Faulty Transceivers)	Medium
Software Configuration Errors or Incompatibilities	Low

Diagnostic Commands

```
display this
display version
display optical transceiver
display interface
debug enable
debug interface
```

Resolution Steps

- Step 1: {'Step': '1. Inspect Physical Connections', 'Action': 'Verify that all fiber optic cables are securely connected and terminated at both ends.'}
- Step 2: {'Step': '2. Check Optical Transceivers', 'Action': 'Verify that the optical transceivers are properly aligned and not damaged. Replace if necessary.'}
- Step 3: {'Step': '3. Review Software Configuration', 'Action': 'Verify that the software configuration is correct and compatible with the switch model. Update if necessary.'}
- Step 4: {'Step': '4. Perform a System Restart', 'Action': 'Restart the system to ensure that any changes take effect.'}
- Step 5: {'Step': '5. Verify Alarm Status', 'Action': 'Verify that the alarm is cleared after implementing the above steps.'}

Post-Check Verification

```
display this
display version
display alarm
display interface
debug disable
```