

Huawei Access Switch Node Delhi-NCR-12 Alarm Handling SOP

Node: Huawei-Access-Delhi-NCR-12 | **Vendor:** Huawei | **Severity:** Major | **Alarm Code:** ALARM_3304

Description

Handling ALARM_3304 on Huawei-Access-Delhi-NCR-12 Access Switch to mitigate impact on network reliability and performance.

Potential Root Causes

Cause	Probability
Optical interface error due to faulty fiber or connector	High
Software issues with the Optical interface module	Medium
Hardware malfunction of the Optical interface module	Low

Diagnostic Commands

```
display diagnostic result interface GigabitEthernet0/0/1
verify interface GigabitEthernet0/0/1 status
display optical module information
display optical interface information
```

Resolution Steps

Step 1: {'Step': 'Isolate the issue by checking the optical interface status', 'Action': 'issuecommand: display diagnostic result interface GigabitEthernet0/0/1'}

Step 2: {'Step': 'Verify the interface status and troubleshoot any issues', 'Action': 'issuecommand: verify interface GigabitEthernet0/0/1 status'}

Step 3: {'Step': 'Replace the faulty optical module if necessary', 'Action': 'physicallyreplace: optical module'}

Step 4: {'Step': 'Perform a software upgrade if a software issue is identified', 'Action': 'issuecommand: upgrade system software'}

Step 5: {'Step': 'Notify the maintenance team for further assistance if the issue persists', 'Action': 'notifyteam: maintenance'}

Post-Check Verification

```
verify interface GigabitEthernet0/0/1 status
display diagnostic result interface GigabitEthernet0/0/1
display system status
```