

Huawei Access Switch - ALARM_5302

Troubleshooting SOP

Node: Huawei-Access-Delhi-NCR-12 | **Vendor:** Huawei | **Severity:** Major | **Alarm Code:** ALARM_5302

Description

Major Alarm on Huawei Access Switch Node ID: Huawei-Access-Delhi-NCR-12 - ALARM_5302: Unexpected Link Down

Potential Root Causes

Cause	Probability
Optical Fiber Cut or Damaged	High
Cable or Connector Fault	Medium
Wrong Configuration or Settings	Low

Diagnostic Commands

```
display fiber-link
display link-status
display device-capability
display system-internal-diag
```

Resolution Steps

- Step 1: {'Step': 'Check Physical Connections', 'Action': 'Verify all fiber optic cables and connectors for any signs of damage or wear.'}
- Step 2: {'Step': 'Run Diagnostic Tests', 'Action': 'Use the display fiber-link and display link-status commands to check for any issues with the fiber links.'}
- Step 3: {'Step': 'Verify Configuration', 'Action': 'Check the device configuration and settings for any mistakes or inconsistencies.'}
- Step 4: {'Step': 'Replace or Repair Faulty Components', 'Action': 'Replace or repair any faulty components or cables as identified by the diagnostic tests.'}

Post-Check Verification

```
display fiber-link
display link-status
```

```
display system-internal-diag
```