

Huawei Access Switch Node

(Huawei-Access-Delhi-NCR-12) - ALARM_5529 Minor Alarm Resolution SOP

Node: Huawei-Access-Delhi-NCR-12 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_5529

Description

This SOP outlines the steps to resolve the ALARM_5529 minor alarm on the Huawei Access Switch Node (Huawei-Access-Delhi-NCR-12). The alarm is triggered due to a minor issue.

Potential Root Causes

Cause	Probability
Optical Fiber Damage	High
Wavelength Mismatch	Medium
Transceiver Issue	Low

Diagnostic Commands

```
display transceiver
display optical-fiber
display wavelength-mismatch
```

Resolution Steps

- Step 1: {'Step': 1, 'Action': 'Verify the optical fiber connections and check for any damage. Replace the damaged fiber if necessary.', 'CLI_Command': 'display optical-fiber'}
- Step 2: {'Step': 2, 'Action': 'Verify the wavelength settings on both ends of the optical link. Ensure they match.', 'CLI_Command': 'display wavelength-mismatch'}
- Step 3: {'Step': 3, 'Action': 'Replace the transceiver module if necessary.', 'CLI_Command': 'replace transceiver'}

Post-Check Verification

```
display transceiver
display optical-fiber
display wavelength-mismatch
```