

Huawei Access Switch ALARM_9084 Minor Alarm SOP

Node: Huawei-Access-Delhi-NCR-12 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_9084

Description

This SOP describes the steps to diagnose and resolve the ALARM_9084 minor alarm on Huawei Access Switch Node ID: Huawei-Access-Delhi-NCR-12.

Potential Root Causes

Cause	Probability
Optical module failure	High
Cable or connector issue	Medium
Switch software or configuration issue	Low

Diagnostic Commands

```
display version
display diagnose power info
display optical-module info
```

Resolution Steps

- Step 1: {'Step': '1. Replace the faulty optical module', 'Action': "Use the 'replace optical-module' command to replace the faulty module"}
- Step 2: {'Step': '2. Check and replace any damaged cables or connectors', 'Action': 'Verify the integrity of cables and connectors, and replace any damaged ones'}
- Step 3: {'Step': '3. Check the switch software and configuration', 'Action': "Use the 'display version' and 'display current-configuration' commands to verify the software and configuration"}
- Step 4: {'Step': '4. Reset the switch to default settings', 'Action': "Use the 'reset system default' command to reset the switch to its default settings"}

Post-Check Verification

```
display alarm-info
display diagnose power info
display optical-module info
```