

Huawei Access Switch Node ID:

Huawei-Access-Delhi-NCR-16 Alarm Severity:

Warning SOP

Node: Huawei-Access-Delhi-NCR-16 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_1778

Description

This SOP outlines the technical steps to troubleshoot and resolve a Huawei Access Switch alarm with Alarm Code ALARM_1778.

Potential Root Causes

Cause	Probability
Optical Fiber Fault	High
Huawei Access Switch Software Issues	Medium
Misconfigured Port or VLAN Settings	Low

Diagnostic Commands

```
display fabric fabric-name
display evb evb-name
display optics optics-name
```

Resolution Steps

Step 1: {'Step': '1. Verify the alarm status and clear the alarm if it is not critical.', 'CLI_Command': 'display alarm'}

Step 2: {'Step': '2. Check the optical fiber connections and replace the fiber if necessary.', 'CLI_Command': 'display optics optics-name'}

Step 3: {'Step': '3. Check the Huawei Access Switch software configuration and upgrade to the latest version if necessary.', 'CLI_Command': 'display version'}

Step 4: {'Step': '4. Verify the port and VLAN settings and correct any misconfigurations.', 'CLI_Command': 'display interface interface-name'}

Post-Check Verification

```
display alarm
display fabric fabric-name
```

```
display evb evb-name
```