

Huawei Access Switch Node Delhi-NCR-16 Alarm Resolution SOP

Node: Huawei-Access-Delhi-NCR-16 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_7398

Description

This SOP outlines the steps to resolve the ALARM_7398 on Huawei Access Switch Node Delhi-NCR-16.

Potential Root Causes

Cause	Probability
Optical Signal Deterioration	High
Optical Fiber Cut	Medium
Hardware Failure (Switching Module)	Low

Diagnostic Commands

```
display diagnose
display fault
display system view | include ALARM_7398
```

Resolution Steps

- Step 1: {'Step': 'Verify the alarm status', 'Action': "Run command: 'display alarm' and check the alarm status"}
- Step 2: {'Step': 'Check the optical signal level', 'Action': "Run command: 'display optical signal' and verify the signal level"}
- Step 3: {'Step': 'Check for optical fiber cuts', 'Action': 'Verify the fiber connections and check for any cuts or damage'}
- Step 4: {'Step': 'Replace the switching module (if necessary)', 'Action': "Run command: 'system view' and 'undo shutdown port 1/1/1/1' to replace the switching module"}
- Step 5: {'Step': 'Verify the system after replacement', 'Action': "Run command: 'display system view' and verify the system status"}

Post-Check Verification

```
display system view | include ALARM_7398
```

```
display fault  
display diagnose
```