

Huawei Access Switch Minor Alarm Resolution SOP - Node ID: Huawei-Access-Delhi-NCR-16

Node: Huawei-Access-Delhi-NCR-16 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_9498

Description

The Huawei-Access-Delhi-NCR-16 access switch has triggered a minor alarm with alarm code ALARM_9498. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Optical fiber cut or damage	High
Switching module failure	Medium
Cable or connector issue	Low

Diagnostic Commands

```
display current-alarms
display alarm-history
display interface status
display optical-fiber status
```

Resolution Steps

- Step 1: {'Step': 'Verify the alarm details', 'Action': "Run the command 'display current-alarms' and 'display alarm-history' to gather information about the alarm."}
- Step 2: {'Step': 'Check the interface status', 'Action': "Run the command 'display interface status' to verify the status of the interface associated with the alarm."}
- Step 3: {'Step': 'Verify the optical fiber status', 'Action': "Run the command 'display optical-fiber status' to verify the status of the optical fiber associated with the alarm."}
- Step 4: {'Step': 'Replace the optical fiber or switching module if necessary', 'Action': "Replace the faulty optical fiber or switching module as per the manufacturer's instructions."}

Post-Check Verification

```
display current-alarms
display alarm-history
```

```
display interface status  
display optical-fiber status
```