

SOP: Troubleshooting Huawei Access Switch - ALARM_9531 in Delhi NCR Node

Node: Huawei-Access-Delhi-NCR-16 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_9531

Description

This SOP outlines the steps to troubleshoot and resolve the ALARM_9531 (Minor Severity) issue on Huawei Access Switch in Delhi NCR Node (Node ID: Huawei-Access-Delhi-NCR-16) with Vendor: Huawei and Role: Access Switch.

Potential Root Causes

Cause	Probability
Power supply failure or voltage fluctuation	Medium
Switch firmware or software issues	High
Cable or connector issues	Low

Diagnostic Commands

```
display version
display power
display env temperature
display fan
display sys fault
```

Resolution Steps

Step 1: {'Step': 'Check power supply and voltage levels', 'Action': 'Run display power command to check power supply and voltage levels. Verify that power supply is functioning correctly and voltage levels are within the specified range.'}

Step 2: {'Step': 'Update switch firmware or software', 'Action': 'Run upgrade package command to update switch firmware or software to the latest version. Verify that the update is successful and the switch is functioning correctly.'}

Step 3: {'Step': 'Check cables and connectors', 'Action': 'Inspect cables and connectors for any signs of damage or wear. Replace any damaged cables or connectors and verify that the issue is resolved.'}

Post-Check Verification

```
display version
```

```
display power  
display sys status
```