

Huawei Access Switch Node Delhi-NCR-22 Alarm SOP (ALARM_1786)

Node: Huawei-Access-Delhi-NCR-22 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_1786

Description

This SOP outlines the steps to diagnose and resolve the ALARM_1786 warning alarm on Huawei Access Switch Node Delhi-NCR-22.

Potential Root Causes

Cause	Probability
High CPU utilization on the switch	High
Insufficient memory on the switch	Medium
Misconfigured QoS policies	Low

Diagnostic Commands

```
display cpu usage
display memory usage
display qos policy
```

Resolution Steps

- Step 1: {'Step': 'Check CPU usage and optimize if necessary', 'Action': "Use the 'display cpu usage' command to check CPU utilization. If high, optimize CPU-intensive processes or add more resources to the switch."}
- Step 2: {'Step': 'Check memory usage and optimize if necessary', 'Action': "Use the 'display memory usage' command to check memory usage. If low, optimize memory-intensive processes or add more memory to the switch."}
- Step 3: {'Step': 'Review QoS policies', 'Action': "Use the 'display qos policy' command to review QoS policies. If misconfigured, reconfigure QoS policies according to the requirements."}

Post-Check Verification

```
display cpu usage
display memory usage
display qos policy
```