

Huawei Access Switch Alarm Resolution SOP

Node: Huawei-Access-Delhi-NCR-22 | **Vendor:** Huawei | **Severity:** Major | **Alarm Code:** ALARM_5463

Description

This SOP outlines the steps to resolve the ALARM_5463 on Huawei Access Switch Node ID: Huawei-Access-Delhi-NCR-22.

Potential Root Causes

Cause	Probability
Optical Module Failure	High
Cable Damage or Fault	Medium
Incorrect Fiber Configuration	Low

Diagnostic Commands

```
display device all
display fiber optic all
display interface all
```

Resolution Steps

- Step 1: {'Step': '1. Replace the faulty Optical Module', 'CLI_Command': 'slot replace module '}
- Step 2: {'Step': '2. Verify the cable connections and replace if damaged', 'CLI_Command': 'display interface '}
- Step 3: {'Step': '3. Reconfigure the fiber connections', 'CLI_Command': 'system-view\ninterface \nport link-type fiber-optic\nport fiber-connector-type'}

Post-Check Verification

```
display device all
display fiber optic all
display interface all
```