

Huawei Access Switch Node Delhi-NCR-22: Resolving ALARM_7781

Node: Huawei-Access-Delhi-NCR-22 | **Vendor:** Huawei | **Severity:** Major | **Alarm Code:** ALARM_7781

Description

ALARM_7781 is a Major alarm indicating a potential issue with the Huawei Access Switch Node at Delhi-NCR-22.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Bug or Config Issue	Medium
Environmental Factors (Temperature, Power, etc.)	Low

Diagnostic Commands

```
display alarm
display device
display power supply
display fan
display temperature
```

Resolution Steps

- Step 1: {'Step': 1, 'Action': 'Check the alarm logs to identify the root cause'}
- Step 2: {'Step': 2, 'Action': 'Verify the hardware and software configurations for any discrepancies'}
- Step 3: {'Step': 3, 'Action': 'Replace the faulty hardware component (if identified)'}
- Step 4: {'Step': 4, 'Action': "Run the command 'reset system' to restart the switch"}
- Step 5: {'Step': 5, 'Action': 'Verify that the alarm has cleared after the restart'}

Post-Check Verification

```
display alarm
display device
display power supply
```

```
display fan  
display temperature
```