

Huawei Access Switch Alarm Handling SOP:

ALARM_2360

Node: Huawei-Access-Delhi-NCR-24 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_2360

Description

Alarm ALARM_2360 is triggered on Huawei-Access-Delhi-NCR-24 with a Severity of Warning. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Optical Module Fault	High
Cable or Fiber Cut	Medium
Incorrect Optics Configuration	Low

Diagnostic Commands

```
display optical-module
display interface
display transceiver
```

Resolution Steps

- Step 1: {'Step': '1. Check the Optical Module Status', 'Action': "Use the command 'display optical-module' to verify the status of the optical module. Replace the module if faulty."}
- Step 2: {'Step': '2. Verify the Fiber Connection', 'Action': 'Use a fiber tester to verify the integrity of the fiber connection.'}
- Step 3: {'Step': '3. Re-Configure Optics', 'Action': "Use the command 'undo optics default' followed by 'optics default' to re-configure the optics settings."}

Post-Check Verification

```
display optical-module
display interface
display transceiver
```