

Huawei Access Switch Alarm SOP for ALARM_2522

Node: Huawei-Access-Delhi-NCR-24 | **Vendor:** Huawei | **Severity:** Critical | **Alarm Code:** ALARM_2522

Description

This SOP outlines the steps to diagnose, resolve, and verify the fix for the Huawei Access Switch Alarm ALARM_2522.

Potential Root Causes

Cause	Probability
Hardware failure in the switch	High
Software bug or misconfiguration	Medium
Power supply issues	Low

Diagnostic Commands

```
display alarm
display error
show power supply status
```

Resolution Steps

- Step 1: {'Step': 'Check the hardware for any physical damage or faults', 'Action': 'Verify the status of the switch and its components', 'CLI_Command': 'display hardware info'}
- Step 2: {'Step': 'Check the software version and configuration', 'Action': 'Verify the software version and configuration of the switch', 'CLI_Command': 'display version'}
- Step 3: {'Step': 'Check the power supply status', 'Action': 'Verify the power supply status of the switch', 'CLI_Command': 'show power supply status'}
- Step 4: {'Step': 'Perform a hard reset of the switch', 'Action': 'Perform a hard reset of the switch to default settings', 'CLI_Command': 'reset system'}

Post-Check Verification

```
display alarm
display error
show power supply status
```