

Huawei Access Switch Node Delhi-NCR-24

ALARM_9710 Warning Alarm SOP

Node: Huawei-Access-Delhi-NCR-24 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_9710

Description

The ALARM_9710 warning alarm on Huawei Access Switch Node Delhi-NCR-24 indicates a potential issue with the switch's hardware or software components.

Potential Root Causes

Cause	Probability
Overheating CPU	High
Memory Issues	Medium
Switch Software Bugs	Low

Diagnostic Commands

```
display version
display diagnostic result
display temperature
display cpu usage
```

Resolution Steps

- Step 1: {'Step': '1. Check the CPU temperature and ensure it is within normal operating range.', 'Action': "Check the output of 'display temperature' command."}
- Step 2: {'Step': '2. Check the CPU usage and ensure it is within normal operating range.', 'Action': "Check the output of 'display cpu usage' command."}
- Step 3: {'Step': '3. If overheating CPU is detected, shutdown the switch and perform a hardware inspection.', 'Action': "Execute the 'shutdown' command using the console."}
- Step 4: {'Step': '4. If memory issues are detected, restart the switch and check for any software bugs.', 'Action': "Execute the 'restart' command using the console."}
- Step 5: {'Step': '5. If software bugs are detected, upgrade the switch software to the latest version.', 'Action': "Execute the 'upgrade software' command using the console."}

Post-Check Verification

```
display version  
display diagnostic result  
display temperature  
display cpu usage
```