

Huawei Access Switch SOP for Alarm Code

ALARM_9802

Node: Huawei-Access-Delhi-NCR-24 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_9802

Description

This SOP outlines the steps to diagnose, resolve, and verify a minor alarm on the Huawei Access Switch with Node ID: Huawei-Access-Delhi-NCR-24, Vendor: Huawei, Role: Access Switch, Alarm Code: ALARM_9802, and Severity: Minor.

Potential Root Causes

Cause	Probability
High Temperature on the Switch	High
Fan Failure	Medium
Power Supply Issue	Low

Diagnostic Commands

```
display current-temperature
display fan-status
display power-supply-status
```

Resolution Steps

- Step 1: {'Step': 'Check the switch temperature and ensure it is within the specified range.', 'Action': 'display current-temperature'}
- Step 2: {'Step': 'Verify the fan status and replace the fan if it is faulty.', 'Action': 'display fan-status && replace-fan'}
- Step 3: {'Step': 'Check the power supply status and replace the power supply if it is faulty.', 'Action': 'display power-supply-status && replace-power-supply'}
- Step 4: {'Step': 'After resolving the issue, restart the switch.', 'Action': 'restart system'}

Post-Check Verification

```
display alarm-list
```