

Huawei Access Switch SOP for Alarm Code

ALARM_9973

Node: Huawei-Access-Delhi-NCR-24 | **Vendor:** Huawei | **Severity:** Major | **Alarm Code:** ALARM_9973

Description

This SOP outlines the procedures to diagnose and resolve the ALARM_9973 on Huawei Access Switch - Huawei-Access-Delhi-NCR-24.

Potential Root Causes

Cause	Probability
Optical fiber cut or damage	High
Transceiver module failure	Medium
Incorrect fiber optic cable connection	Low

Diagnostic Commands

```
display fiber optic cable info
display transceiver info
display optical interface info
```

Resolution Steps

- Step 1: {'Step': 'Check the fiber optic cable connection', 'Action': 'Verify that the fiber optic cable is securely connected to the correct ports on the switch and optical network unit (ONU)', 'CLI_Command': 'display fiber optic cable info'}
- Step 2: {'Step': 'Inspect the transceiver module', 'Action': 'Check the transceiver module for any signs of physical damage or degradation', 'CLI_Command': 'display transceiver info'}
- Step 3: {'Step': 'Replace the optical interface', 'Action': 'Replace the faulty optical interface with a new one', 'CLI_Command': 'undo optical interface {[interface-name]}'}

Post-Check Verification

```
display fiber optic cable info
display transceiver info
display optical interface info
```