

Huawei Access Switch Alarm Resolution SOP - ALARM_4862

Node: Huawei-Access-Kolkata-WB-120 | **Vendor:** Huawei | **Severity:** Major | **Alarm Code:** ALARM_4862

Description

This SOP outlines the steps to resolve a Huawei access switch alarm ALARM_4862. The alarm indicates a potential issue on the Node ID: Huawei-Access-Kolkata-WB-120, which is an Access Switch from Huawei.

Potential Root Causes

Cause	Probability
Incorrect Configuration	High
Hardware Failure	Medium
Software Issue	Low

Diagnostic Commands

```
display alarm
display error
display logbuf
show system internal alarm
```

Resolution Steps

- Step 1: {'Step': 'Check the alarm log for any relevant information', 'Action': 'Use the command "display logbuf" to view the system log buffer.'}
- Step 2: {'Step': 'Verify the configuration', 'Action': 'Use the command "display current-configuration" to verify the configuration of the device.'}
- Step 3: {'Step': 'Check for hardware issues', 'Action': 'Use the command "display hardware" to verify the hardware status of the device.'}
- Step 4: {'Step': 'Reload the software', 'Action': 'Use the command "reload" to reload the software of the device.'}
- Step 5: {'Step': 'Replace the faulty component', 'Action': 'If the issue is caused by hardware failure, replace the faulty component.'}

Post-Check Verification

```
display alarm  
display error  
display logbuf  
show system internal alarm
```