

Huawei Access Switch Node ID: Huawei-Access-Kolkata-WB-120 Alarm Resolution SOP

Node: Huawei-Access-Kolkata-WB-120 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_8575

Description

This SOP outlines the steps to diagnose and resolve the ALARM_8575 (Warning) on Huawei Access Switch Node ID: Huawei-Access-Kolkata-WB-120.

Potential Root Causes

Cause	Probability
Physical Layer Issues (e.g., cable damage, port mismatch)	Medium
Software Configuration Issues (e.g., incorrect port settings, VLAN mismatch)	High
Hardware Faults (e.g., faulty SFP, port failure)	Low

Diagnostic Commands

```
display current-configuration
display interface status
display ethernetswitching port info
display cpu-memory usage
```

Resolution Steps

- Step 1: {'Step': 'Verify physical connections and ensure they are secure and undamaged.', 'CLI_Commands': []}
- Step 2: {'Step': 'Check and correct software configuration settings (e.g., port settings, VLAN settings) as required.', 'CLI_Commands': ['undo port default vlan', 'set port vlan 10']}
- Step 3: {'Step': 'Replace faulty hardware components (e.g., SFP, port) as required.', 'CLI_Commands': []}
- Step 4: {'Step': 'Clear the alarm using the following command.', 'CLI_Commands': ['reset alarm info']}

Post-Check Verification

```
display alarm info
display interface status
```

```
display ethernetswitching port info
```