

Huawei Access Switch Node - ALARM_7795 Minor Alarm Troubleshooting SOP

Node: Huawei-Access-Kolkata-WB-130 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_7795

Description

This SOP outlines the steps to diagnose and resolve the Huawei Access Switch Node (Node ID: Huawei-Access-Kolkata-WB-130) minor alarm ALARM_7795.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Insufficient Memory	Medium
Misconfigured Firewall Rules	Low

Diagnostic Commands

```
display cpu-usage
display memory-info
display firewall-rule
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU Utilization', 'Task': "Verify CPU utilization using the 'display cpu-usage' command.", 'Action': 'If CPU utilization is high, consider upgrading hardware or adjusting system settings.'}
- Step 2: {'Step': '2. Check Memory Usage', 'Task': "Verify memory usage using the 'display memory-info' command.", 'Action': 'If memory is insufficient, consider adding more memory or adjusting system settings.'}
- Step 3: {'Step': '3. Check Firewall Rules', 'Task': "Verify firewall rules using the 'display firewall-rule' command.", 'Action': 'If firewall rules are misconfigured, update the rules to resolve the issue.'}

Post-Check Verification

```
display cpu-usage
display memory-info
display firewall-rule
```