

SOP - Huawei-Access-Kolkata-WB-132 Alarm 5292 Handling

Node: Huawei-Access-Kolkata-WB-132 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_5292

Description

Huawei Access Switch (Node ID: Huawei-Access-Kolkata-WB-132) Alarm 5292 - Warning, indicating a potential issue with the switch.

Potential Root Causes

Cause	Probability
Hardware failure in the switch	High
Software issue with the switch firmware	Medium
Cable or connectivity issue between the switch and the network	Low

Diagnostic Commands

```
display version
display diagnostic information
diag -f
show interface
```

Resolution Steps

- Step 1: {'Step': 'Check the switch logs for any error messages', 'Action': 'show log', 'Expected Output': 'Error messages indicating a hardware or software issue'}
- Step 2: {'Step': 'Verify the switch hardware and firmware version', 'Action': 'display version', 'Expected Output': 'Correct hardware and firmware version'}
- Step 3: {'Step': 'Check the cable and connectivity between the switch and the network', 'Action': 'show interface', 'Expected Output': 'All ports are up and functioning correctly'}
- Step 4: {'Step': 'Reset the switch to factory defaults', 'Action': 'reset system', 'Expected Output': 'Switch is reset to factory defaults'}

Post-Check Verification

```
display version
display diagnostic information
```

```
show interface  
show log
```