

Huawei Access Switch Alarm Resolution SOP - ALARM_9282

Node: Huawei-Access-Kolkata-WB-132 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_9282

Description

Minor alarm on Huawei Access Switch Node ID: Huawei-Access-Kolkata-WB-132 indicating a potential issue.

Potential Root Causes

Cause	Probability
Link Flapping or Interface Misconfiguration	High
Software or Firmware Issues	Medium
Environmental Factors or Equipment Malfunction	Low

Diagnostic Commands

```
display current-configuration interface GigabitEthernet0/0/0
display interface GigabitEthernet0/0/0
show environment
show tech-support
```

Resolution Steps

- Step 1: {'Step': 'Verify interface configuration and make necessary changes', 'CLI_Command': 'undo interface GigabitEthernet0/0/0'}
- Step 2: {'Step': 'Check for software or firmware issues and update if necessary', 'CLI_Command': 'system software save'}
- Step 3: {'Step': 'Replace equipment if environmental factors or malfunction is suspected', 'Action': 'Replace the affected device'}

Post-Check Verification

```
display interface GigabitEthernet0/0/0
show environment
show tech-support
```