

Huawei Access Switch Mumbai Node (MH-42) Alarm Handling SOP for ALARM_4181

Node: Huawei-Access-Mumbai-MH-42 | **Vendor:** Huawei | **Severity:** Critical | **Alarm Code:** ALARM_4181

Description

Alarm Code ALARM_4181 indicates a critical issue with the Huawei Access Switch at Node ID Huawei-Access-Mumbai-MH-42. This SOP outlines the procedures to diagnose and resolve this alarm.

Potential Root Causes

Cause	Probability
Hardware failure in the Access Switch	High
Software bug in the Access Switch operating system	Medium
Misconfiguration of the Access Switch	Low

Diagnostic Commands

```
display current-configuration
display error-message
debug enable
debug bgp
show bgp summary
```

Resolution Steps

- Step 1: {'Step': 'Power cycle the Access Switch', 'Description': 'Perform a power cycle of the Access Switch to clear any transient issues.', 'CLI_Commands': ['power-cycle']}
- Step 2: {'Step': 'Check and replace faulty hardware', 'Description': 'Verify the hardware for any signs of damage or failure and replace it if necessary.', 'CLI_Commands': []}
- Step 3: {'Step': 'Perform a software upgrade', 'Description': 'Upgrade the Access Switch operating system to the latest version to resolve any software bugs.', 'CLI_Commands': ['upgrade package']}
- Step 4: {'Step': 'Verify Access Switch configuration', 'Description': 'Verify the Access Switch configuration for any misconfigurations and correct it if necessary.', 'CLI_Commands': ['display current-configuration']}

Post-Check Verification

```
show bgp summary
```

```
show ip interface brief
display error-message
display current-configuration
```