

Huawei Access Switch Mumbai Node Minor Alarm Resolution SOP

Node: Huawei-Access-Mumbai-MH-42 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_4692

Description

This SOP outlines the steps to resolve a minor alarm on the Huawei Access Switch Mumbai node, triggered by alarm code ALARM_4692. The alarm indicates a minor issue with the switch.

Potential Root Causes

Cause	Probability
Physical Interface Issue	Medium
Software Configuration Error	Low
Hardware Component Failure	Low

Diagnostic Commands

```
display alarm
display interface
display error-message enable
display swi-mem
display cpu-mem
```

Resolution Steps

- Step 1: {'Step': '1. Check the alarm log for details of the issue', 'Action': 'display alarm'}
- Step 2: {'Step': '2. Verify the interface status', 'Action': 'display interface'}
- Step 3: {'Step': '3. Check for software configuration errors', 'Action': 'display error-message enable'}
- Step 4: {'Step': '4. Check system memory usage', 'Action': 'display swi-mem'}
- Step 5: {'Step': '5. Check CPU usage', 'Action': 'display cpu-mem'}
- Step 6: {'Step': '6. If the issue is software-related, update the software to the latest version', 'Action': 'system update package'}
- Step 7: {'Step': '7. If the issue is hardware-related, replace the faulty component', 'Action': 'service replace component'}

Post-Check Verification

```
display alarm
display interface
display swi-mem
display cpu-mem
```