

Huawei Access Switch Alarm ALARM_5563

Resolution SOP

Node: Huawei-Access-Mumbai-MH-42 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_5563

Description

This SOP outlines the steps to identify and resolve the Huawei Access Switch alarm ALARM_5563, which is of minor severity.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Misconfiguration	Medium
Environmental Factors	Low

Diagnostic Commands

```
display faultman info
display device man info
show version
show hardware version
```

Resolution Steps

- Step 1: {'Step': 'Step 1: Verify Hardware Status', 'Action': "Use the 'display device man info' command to check the status of the hardware components."}
- Step 2: {'Step': 'Step 2: Check Software Configuration', 'Action': "Use the 'display faultman info' command to check for any software-related issues and 'show version' and 'show hardware version' commands to verify the software and hardware versions are compatible."}
- Step 3: {'Step': 'Step 3: Perform Hardware Replacement', 'Action': 'If the hardware issue persists, replace the faulty hardware component and verify the alarm is cleared.'}
- Step 4: {'Step': 'Step 4: Reconfigure Software', 'Action': 'If the software configuration issue persists, reconfigure the software to the latest version and verify the alarm is cleared.'}

Post-Check Verification

```
display faultman info
display device man info
```

```
show version
show hardware version
```