

Huawei Access Switch Alarm SOP - ALARM_8403

Node: Huawei-Access-Mumbai-MH-42 | **Vendor:** Huawei | **Severity:** Critical | **Alarm Code:** ALARM_8403

Description

This is a technical SOP for Huawei Access Switch Node ID: Huawei-Access-Mumbai-MH-42 with Vendor: Huawei, Role: Access Switch, Alarm Code: ALARM_8403, Severity: Critical.

Potential Root Causes

Cause	Probability
Optical Port Fault	High
Optical Fiber Cut	Medium
Switch Port Error	Low

Diagnostic Commands

```
display this
display int qiqabitethernet 0/0/1
display error-message
```

Resolution Steps

- Step 1: {'Step': '1. Verify the optical port status', 'Description': "Check if the optical port is faulty using the 'display this' command.", 'Command': 'display this'}
- Step 2: {'Step': '2. Identify the faulty fiber', 'Description': "Use the 'display int gigabitethernet 0/0/1' command to check if the fiber is cut.", 'Command': 'display int gigabitethernet 0/0/1'}
- Step 3: {'Step': '3. Reset the switch port', 'Description': "Use the 'reset interface gigabitethernet 0/0/1' command to reset the switch port.", 'Command': 'reset interface gigabitethernet 0/0/1'}

Post-Check Verification

```
display interface qiqabitethernet 0/0/1
display error-message
display this
```