

Huawei Access Switch - ALARM_4385 Warning SOP

Node: Huawei-Access-Mumbai-MH-48 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_4385

Description

This Standard Operating Procedure (SOP) outlines the steps to diagnose, resolve, and verify the fix for Alarm Code ALARM_4385 on Huawei Access Switch Node ID: Huawei-Access-Mumbai-MH-48. The alarm is triggered due to a high CPU utilization, which may impact system performance.

Potential Root Causes

Cause	Probability
High CPU utilization due to software or hardware issues	High
Insufficient memory or resource allocation	Medium
Malfunctioning or misconfigured cards or interfaces	Low

Diagnostic Commands

```
display cpu utilization
display memory information
display device card information
display interface statistics
```

Resolution Steps

- Step 1: {'Step': 'Check CPU utilization on the switch and identify the process causing high CPU usage', 'Actions': ['Use the display cpu utilization command to monitor CPU utilization', 'Identify the process causing high CPU usage and investigate the reason for its high CPU usage']}
- Step 2: {'Step': 'Check memory information on the switch and free up any available memory', 'Actions': ['Use the display memory information command to check available memory', 'Free up any available memory by deleting unnecessary files or processes']}
- Step 3: {'Step': 'Check device card information on the switch and replace any malfunctioning cards', 'Actions': ['Use the display device card information command to check card status', 'Replace any malfunctioning cards or interfaces']}
- Step 4: {'Step': 'Configure cards or interfaces to optimize performance', 'Actions': ['Configure cards or interfaces to optimize performance using the relevant Huawei CLI commands']}

Post-Check Verification

```
display cpu utilization
```

```
display memory information  
display device card information  
display interface statistics
```