

Huawei Access Switch Minor Alarm SOP - ALARM_7046

Node: Huawei-Access-Mumbai-MH-48 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_7046

Description

This SOP outlines the steps to diagnose and resolve the ALARM_7046 on Huawei Access Switch Node ID: Huawei-Access-Mumbai-MH-48

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Bug	Medium
Configuration Error	Low

Diagnostic Commands

```
display current-configuration | include alarm
display device info
display board info
```

Resolution Steps

- Step 1: {'Step': '1. Check the system logs for any error messages related to ALARM_7046', 'Action': 'show log info'}
- Step 2: {'Step': '2. Verify the switch's hardware status', 'Action': 'display device info'}
- Step 3: {'Step': '3. Check the switch's configuration for any errors', 'Action': 'display current-configuration | include alarm'}
- Step 4: {'Step': '4. Perform a hardware reset (if necessary)', 'Action': 'reset system'}
- Step 5: {'Step': '5. Reboot the switch (if necessary)', 'Action': 'reboot'}

Post-Check Verification

```
display current-configuration | include alarm
display device info
ping test
```