

SOP for Resolving Huawei Access Switch Alarm

ALARM_4409

Node: Huawei-Access-Mumbai-MH-50 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_4409

Description

Huawei Access Switch Alarm ALARM_4409 indicates a minor issue related to the switch's internal configuration or hardware.

Potential Root Causes

Cause	Probability
Hardware Failure	Medium
Misconfigured Switch Ports	High
Software Issues	Low

Diagnostic Commands

```
display version
display current-configuration
display device-manage fault-info
```

Resolution Steps

- Step 1: {'Step': 'Check switch logs for any critical errors', 'Action': 'display log'}
- Step 2: {'Step': 'Verify switch port configurations', 'Action': 'display interface'}
- Step 3: {'Step': 'Check for hardware failure', 'Action': 'display device-manage fault-info'}
- Step 4: {'Step': 'Reboot the switch if necessary', 'Action': 'shutdown 10'}
- Step 5: {'Step': 'Verify switch functionality post-resolution', 'Action': 'ping 192.168.1.1'}

Post-Check Verification

```
display interface
display current-configuration
ping 192.168.1.1
```